


C15 Firmware Update 25-39 - What's New?

Reworked Recorder

The internal audio recorder has been thoroughly reworked:

- Significantly faster loading times and overall improved performance.
- Added time markers for session starts and recording pauses.
- Enhanced **zooming and scrolling** for better navigation.
- Increased time-axis resolution for more precise editing.
- Fixed rare issues where recording could unexpectedly stop.



Improved Audio Rendering

• Fixed an issue where disabling the C15 WiFi network could cause audible glitches.

Bugfixes & Usability Enhancements

- Improved: The display now always reopens the last screen after startup (not just the last parameter screen).
- Fixed: Dragging multiple presets to the last bank position in the Graphical UI caused a shift in numbering.
- Fixed: Change indication (asterisk) on presets showed sometimes incorrectly after loading.
- Fixed: Ribbon used in Edit Mode did not show the value on the base unit's display.
- Fixed: Layer Sound signal flow did not displayed correctly on the main screen.
- Fixed: Routing LED indication for assigned MCs did not displayed correctly when Part II was selected.
- Fixed: Using Sostenuto in a Split Sound caused hanging notes under certain circumstances.
- Fixed: Direct Load stopped working after copy-pasting a bank in the Graphical UI.
- Fixed: In rare cases, up to 24 unison voices could be set for a Layer Sound.
- Fixed: Converting a Layer Sound to a Split Sound caused a gap on the (virtual) keyboard

Revised manual (PDF)

• The C15 User's Manual has been improved and updated, reflecting the latest firmware changes.

Other Improvements

- + Bugfixes
- + Performance enhancements
- + Usability improvements